

! (Ni S0 " 6H! 0)	# 98. 5%	# 98. 0%	99. 2%
\$ %&'	(0. 01%	(0. 02%) 0. 01%
* + ' (Cl)	(0. 001%	(0. 005%) 0. 001%
, - . (NO")	(0. 003%	(0. 02%) 0. 003%
/ (Na)	(0. 02%	(0. 05%) 0. 02%
O(Ca)	(0. 02%	(0. 1%) 0. 02%
1 (Fe)	(0. 001%	(0. 005%) 0. 001%
2(Co)	(0. 01%	(0. 05%) 0. 01%
3(Cu)	(0. 002%	(0. 005%) 0. 002%
4(Zn)	(0. 01%	(0. 05%) 0. 01%
5(Pb)	(0. 002%	(0. 005%) 0. 002%